

## Interest in alteration options

1 = Definitely interested, well worth pursuing

2 = Fairly interested, happy to hear more.

3 = Not interested at all, not worth pursuing.

Columns 1, 2, and 3 display votes cast, with %1, %2 and %3 indicating the relevant percentages.

	<b>1</b>	<b>2</b>	<b>3</b>	<b>%1</b>	<b>%2</b>	<b>%3</b>
Replace external wooden doors with glass doors	29	3	0	91	9	0
Add wheelchair access to the main entrance	11	16	5	34	50	16
Create one porch out of the present three	30	2	0	94	6	0
Strengthen the porch ceiling, providing proper access to the balcony	29	2	1	91	6	3
Glaze all or part of the internal porch wall	23	9	0	72	28	0
Re-site lighting and sound controls in the balcony	21	10	1	66	31	3
Install emergency lighting	22	8	2	69	25	6
Strip and treat (or even re-lay) the wooden floor	5	10	17	16	31	53
Replace present windows with double-glazed alternatives	8	13	11	25	41	34
Add black-out facilities to the windows	12	12	8	38	38	25
Replace the pews with chairs	5	6	21	16	19	66
Redesign the pulpit and choir stalls area	17	9	6	53	28	19